

Rock Toe and Brush Revetment Update.

Mike Harvey



M&T/Llano Seco Fish Screen

complex world

CLEAR SOLUTIONS™



Interim Protection

- Rock-toe and brush revetment
- Constructed October 2007
- ~ 1500 lineal feet
- Top of the rock El. 119'; 15,000 cfs (42 % exceedence)
- Wood incorporated within (~ 12000 cfs) and on top of structure
- Between the rock and bank was backfilled to prevent erosion and fish entrapment

Potential Maintenance Issues: Peaks: 56,000, 43,000, 64,000, 104, 000 cfs

- Flanking of upstream end of the structure
- Loss of rock from the structure due to local scour
- Loss of woody material
- Excessive erosion of upper bank
- Excessive erosion off the downstream end of the structure



Upstream end of the site prior to construction



Middle part of the site prior to construction



Apex of the eroding bend prior to construction




Middle part of the downstream part of the site prior to construction



24 10 2006

Downstream end of the site prior to construction






Typical
sections of
the rock-
toe/brush
revetment
showing
design
flows and
elevations



Rock and Brush Toe Revetment



View downstream of the rock-toe being emplaced, 2007



View upstream of the rock-toe and woody debris, 2007



Woody debris on top of structure, 2007



Backfill behind rock toe, 2007





**View upstream
of the upstream
end of the
revetment
showing the
presence of the
pre-construction
vegetation on
the upstream
bank**

Woody debris on top of structure, 2008



View downstream of bank erosion caused by Winter 2008 high flows



Woody debris in and on structure in 2008 after high flows



Upstream end of the revetment in 2010



Woody debris piles on top of structure, 2010



Submerged woody debris within the structure, 2010



Woody debris piles on top of structure, 2010



Woody debris pile and new vegetation growth



Upper bank erosion, 2010



Upper bank erosion, but no backfill scour, 2010



Volunteer willow growth, 2010





Downstream part of the revetment, 2010







Downstream end of the revetment and tieback, 2010



ADCP UNIT



Longitudinal Profile Rock/Brush Toe Revetment



Downstream of RTBR

June 2011, ~ 17,000 cfs



Downstream end of RTBR Revetment, June 2011



Lower end of RTBR Revetment

June 2011



Lower end of Apex of RTBR

June 2011



Apex of RTBR Revetment

June 2011



Upper Bank Layback RTBR

June 2011



Brush Pile Recruitment

June 2011



Mid-Upper part of RTBR Revetment

June 2011



Upper part of RTBR Revetment

June 2011



Upstream part of RTBR Revetment

June 2011



Upstream Transition RTBR

June 2011



CONCLUSIONS

- Flanking of upstream end of the structure -- **Intact**
- Loss of rock from the structure due to local scour – **No evidence of loss**
- Loss of woody material -- **Intact**
- Excessive erosion of upper bank -- **No**
- Excessive erosion off the downstream end of the structure -- **No**

